



1,000-hour oil change v. competitor(s) – Most are 200 hour maximum!

No Valve Adjustment

Poly V Belt = 2K+ hours



Altitude Compensations:

- Electronic Control
- Turbo What sets this engine apart is wide range of applications from genset side: geography, elevation
- Market as 15 kW prime



Service Parts





KOHLER. Engines



Scan the QR code if you need more *service option!*